

We made it a  
**3-point press...**  
just to be sure.



>B< Press is quick and easy to fit, ensuring you'll be delivering the job on time. One press and you have a permanent, leak-proof connection you can rely on. No hot works permit, no additional special equipment and a range that will cover every application.



[www.conexbanninger.com](http://www.conexbanninger.com)

Conex | Bänninger  
**>B< Press**